Facility Summary in Daniels County in the City of Flaxville

Location: PRO CO-OP 3

MT Hwy 5 & Main St Flaxville, MT 59222 Daniels Facility Code: 19535
Last Inspected On: 06/17/2021
System Facility ID:10-01331
Operating Permit Renewal Date: 09/28/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Pro Coop Scobey 4064872741

Operator Contact: Tanner Trower 4064872741

Owner/Operator: Pro Coop Scobey

Jason Nasby, UST Class B Operator
Kent Cromwell, UST Class B Operator
Richard Carrier, UST Class B Operator
Tanner Trower, UST Class A Operator
Tanner Trower, UST Class B Global Operator
Tanner Trower, UST Class B Operator

Tank Code	04	Tank Age	31	Tank Installed Date	07/31/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1225	Spill Test Date	11/19/2021	Piping Installed Date	02/01/2013	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	2000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	11/19/2021			ATG Type	Gilbarco-Veeder Root/Other				
Tank Code	05	Tank Age	31	Tank Installed Date	07/31/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1226	Spill Test Date	11/19/2021	Piping Installed Date	02/01/2013	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	2000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

Report Created: 11/1/2022 Page [1] of [8]

		Overfill Test Date	11/19/2021			ATG Type	Gilbarco-Veeder Root/Other				
Tank Code	S6	Tank Age	9	Tank Installed Date	02/01/2013	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5408	Spill Test Date		Piping Installed Date	02/01/2013	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	11/19/2021	Sump Tightness Test Date	11/19/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date	11/19/2021	Line Tightness Test Date	11/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	No
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				
Tank Code	S7	Tank Age	9	Tank Installed Date	02/01/2013	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5409	Spill Test Date		Piping Installed Date	02/01/2013	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	11/19/2021	Sump Tightness Test Date	11/19/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date	11/19/2021	Line Tightness Test Date	11/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	No
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				
Tank Code	S8	Tank Age	9	Tank Installed Date	02/01/2013	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5453	Spill Test Date		Piping Installed Date	02/01/2013	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	11/19/2021	Sump Tightness Test Date	11/19/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No

Capacity	12000	ATG Test Date	Line Tightness Test Date	11/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	No
		Overfill Test Date			ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				

Location: CROMWELLS CONVENIENCE AND PETROLEUM

101 Railroad Ave W

Scobey, MT 59263 Daniels

System Facility ID:10-01223 Op

Facility Code: 19533 Last Inspected On: 09/21/2021 Operating Permit Renewal Date: 03/09/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Cromwells Convenience and Petroleum

Operator Contact: Shane Cromwell

4064872441

Owner/Operator: Cromwells Convenience and Petroleum

Shane Cromwell, UST Class A Operator Shane Cromwell, UST Class B Global Operator

Tank Code	S4	Tank Age	26	Tank Installed Date	05/01/1996	Tank Material	Aboveground Tank	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	2176	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	09/21/2021	Sump Tightness Test Date	09/21/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	5800	ATG Test Date		Line Tightness Test Date	09/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/Red Jacket FXIV				
Tank Code	S5	Tank Age	26	Tank Installed Date	05/01/1996	Tank Material	Aboveground Tank	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	2177	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	09/21/2021	Sump Tightness Test Date	09/21/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No

Report Created: 11/1/2022 Page [3] of [8]

Capacity	12000	ATG Test Date		Line Tightness Test Date	09/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/Red Jacket FXIV				
Tank Code	S6	Tank Age	26	Tank Installed Date	05/01/1996	Tank Material	Aboveground Tank	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	2178	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	09/21/2021	Sump Tightness Test Date	09/21/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel, Dyed	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	09/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/Red Jacket FXID				
Tank Code	S7	Tank Age	26	Tank Installed Date	05/01/1996	Tank Material	Aboveground Tank	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	2179	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	09/21/2021	Sump Tightness Test Date	09/21/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	09/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/Red Jacket FXID				

Location: NEMONT COMMUNICATIONS INC

61 Hwy 13 S Scobey, MT 59263 Daniels

Facility Code: 19682 Last Inspected On: 09/07/2018 Operating Permit Renewal Date: 02/23/2022

System Facility ID:10-13610

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Nemont Communications Inc 4067835654

Operator Contact:

Owner/Operator: Nemont Communications Inc

Page [4] of [8] Report Created: 11/1/2022

Tank Code	01	Tank Age	27	Tank Installed Date	04/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	3293	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Gravity Feed	CP Met Types	
Product	Oil, Waste	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Deferred	Primary Pipe Detection	Deferred	Vapor Recovery	No
Capacity	100	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

Location: PRO CO-OP 1

3 Daniels St

Scobey, MT 59263 Daniels

Facility Code: 19572

Last Inspected On: 06/17/2021 System Facility ID:10-04159 Operating Permit Renewal Date: 06/20/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Pro Coop Scobey 4064872741

Operator Contact: Jason Nasby;Tanner Trower 4064872741

Owner/Operator: Pro Coop Scobey

Jason Nasby, UST Class A Operator
Jason Nasby, UST Class B Operator
Kent Cromwell, UST Class B Operator
Tanner Trower, UST Class A Operator
Tanner Trower, UST Class B Global Operator
Tanner Trower, UST Class B Operator

		•									
Tank Code	S11	Tank Age	14	Tank Installed Date	10/10/2008	Tank Material	Unknown	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	5134	Spill Test Date		Piping Installed Date	06/19/2007	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	10/04/2021	Sump Tightness Test Date	10/04/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No

Report Created: 11/1/2022 Page [5] of [8]

Capacity	3000	ATG Test Date	10/05/2021	Line Tightness Test Date	10/04/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	10/04/2021			ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				
Tank Code	S10	Tank Age	14	Tank Installed Date	10/10/2008	Tank Material	Unknown	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	5699	Spill Test Date		Piping Installed Date	06/19/2007	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	10/04/2021	Sump Tightness Test Date	10/04/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasohol/Etha nol	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	3000	ATG Test Date	10/05/2021	Line Tightness Test Date	10/04/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	10/04/2021			ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				

System Facility ID:10-03710

Location: PRO CO-OP 2

108 1st St

Scobey, MT 59263 Daniels

Facility Code: 19562 Last Inspected On: 06/17/2021

Operating Permit Renewal Date: 06/20/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

 Owner Operator Contact:
 Pro Coop Scobey
 4064872741

 Operator Contact:
 Jason Nasby; Tanner Trower
 4064872741

Owner/Operator: Pro Coop Scobey

Jason Nasby, UST Class A Operator
Jason Nasby, UST Class B Operator
Kent Cromwell, UST Class B Operator
Tanner Trower, UST Class A Operator
Tanner Trower, UST Class B Global Operator
Tanner Trower, UST Class B Operator

Tank Code 04 Tank Age 28 Tank Installed 10/01/1994 Tank Material Cathodically Piping Material Fiberglass Overfill Types Ball Float Valve

Report Created: 11/1/2022 Page [6] of [8]

			L	Date	L		Protected Steel		Reinforced Plastic		L
Tag Number	1227	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	06/19/2021	Sump Tightness Test Date	06/20/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	06/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Vaporless Manufacturing/Va porless LD-2000				
Tank Code	05	Tank Age	28	Tank Installed Date	10/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	1228	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	06/19/2021	Sump Tightness Test Date	06/20/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	06/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Vaporless Manufacturing/Va porless LD-2000				
Tank Code	06	Tank Age	28	Tank Installed Date	10/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	1229	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	06/19/2021	Sump Tightness Test Date	06/20/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	06/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Vaporless Manufacturing/Va porless LD-2000				
Tank Code	07	Tank Age	28	Tank Installed Date	10/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	1230	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No

Tank Status	Currently in	MLLD Test Date	06/19/2021	Sump Tightness	06/20/2021	Catastrophic L.D	Mechanical Line	Piping Type	Pressurized	CP Met Types	Galvanic
	Use			Test Date		Type 3.0	Leak Detector				
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	06/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Vaporless Manufacturing/Va porless LD-2000				
Tank Code	08	Tank Age	28	Tank Installed Date	10/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	1231	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	06/19/2021	Sump Tightness Test Date	06/20/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	06/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Vaporless Manufacturing/Va porless LD-2000				
Tank Code	09	Tank Age	28	Tank Installed Date	10/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	1232	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	06/19/2021	Sump Tightness Test Date	06/20/2021	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	06/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Vaporless Manufacturing/Va porless LD-2000				